

## List of Impacted Devices by MFG and suggested replacements:

| Manufacturer | Model                  | End of Service | Recommended Cisco Replacement | Recommended Poly Replacement | Recommended Yealink Replacement |
|--------------|------------------------|----------------|-------------------------------|------------------------------|---------------------------------|
| Yealink      | CP920                  | 09/30/2026     | —                             | Poly Trio C60                | Yealink CP925                   |
| Yealink      | CP960                  | 09/30/2026     | —                             | Poly Trio C60                | Yealink CP965                   |
| Yealink      | T19P / T21P            | 09/30/2026     | DP9841                        | Poly Edge E100               | T34W                            |
| Yealink      | T23G / T23P            | 09/30/2026     | DP9841                        | Poly Edge E220               | T34W                            |
| Yealink      | T27G / T27P            | 09/30/2026     | DP9851                        | Poly Edge E320 / E350        | T34W                            |
| Yealink      | T29G                   | 09/30/2026     | DP9851                        | Poly Edge E350 / E450        | T34W                            |
| Yealink      | T40G                   | 09/30/2026     | DP9841                        | Poly Edge E220               | T34W                            |
| Yealink      | T41P / T42G            | 09/30/2026     | DP9851                        | Poly Edge E320 / E350        | T73U / T73W                     |
| Yealink      | T46G                   | 09/30/2026     | DP9861                        | Poly Edge E350 / E450        | T73U / T73W                     |
| Yealink      | T48G                   | 09/30/2026     | DP9871                        | CCX600                       | T77U                            |
| Yealink      | T52S                   | 09/30/2026     | DP9851                        | Poly Edge E320 / E350        | T73U / T73W                     |
| Yealink      | T54S                   | 09/30/2026     | DP9861                        | Poly Edge E350 / E450        | T74W / T74U                     |
| Yealink      | T56A                   | 09/30/2026     | DP9871                        | Poly Edge 550                | T87W                            |
| Yealink      | W52P                   | 09/30/2026     | —                             | Poly Rove 30                 | Yealink W76P                    |
| Yealink      | W56P                   | 09/30/2026     | —                             | Poly Rove 40                 | W79P Pro                        |
| Yealink      | CP930                  | 3/31/2027      |                               | Poly Trio 8300               |                                 |
| Yealink      | T41S, T42S, T46S, T48S | 3/31/2027      |                               |                              |                                 |
| Yealink      | W60P, W69P             | 3/31/2027      |                               |                              | W76P, W79P, W79P Pro            |
| Cisco        | PAP2-NA / PAP2T        | 09/30/2026     | Cisco 191 / 192 ATA           | ATA 402                      | —                               |
| Cisco        | SPA122                 | 09/30/2026     | Cisco 191 / 192 ATA           | ATA 402                      | —                               |
| Cisco        | SPA301                 | 09/30/2026     | —                             | Poly Edge E100               | T34W                            |
| Cisco        | SPA303                 | 09/30/2026     | DP9841                        | Poly Edge E220               | T34W                            |

| Manufacturer | Model                | End of Service         | Recommended Cisco Replacement | Recommended Poly Replacement | Recommended Yealink Replacement |
|--------------|----------------------|------------------------|-------------------------------|------------------------------|---------------------------------|
| Cisco        | SPA501G              | 09/30/2026             | DP9841                        | Poly Edge E320 / E350        | T74U                            |
| Cisco        | SPA502G              | 09/30/2026             | DP9841                        | Poly Edge E100               | T74U                            |
| Cisco        | SPA504G              | 09/30/2026             | DP9841                        | Poly Edge E220 / E320        | T74U                            |
| Cisco        | SPA508G              | 09/30/2026             | DP9841 / DP9851               | Poly Edge E320 / E350        | T74U                            |
| Cisco        | SPA509G              | 09/30/2026             | DP9851 / DP9861               | Poly Edge E350 / E450        | T77U                            |
| Cisco        | SPA514G              | 09/30/2026             | DP9841 / DP9851               | Poly Edge E220 / E320        | T77U                            |
| Cisco        | SPA525G              | 09/30/2026             | DP9861 / DP9871               | Poly Edge E320 / E350        | T87W                            |
| Cisco        | SPA921               | 09/30/2026             | DP9841                        | Poly Edge E100 / E220        | T34W                            |
| Cisco        | SPA941               | 09/30/2026             | DP9841                        | Poly Edge E220               | T34W                            |
| Cisco        | SPA942               | 09/30/2026             | DP9841 / DP9851               | Poly Edge E320 / E350        | T34W                            |
| Cisco        | SPA962               | 09/30/2026             | DP9851 / DP9861               | Poly Edge E320 / E350        | T87W                            |
| Cisco        | SPA2102 / SPA3102    | 09/30/2026             | Cisco 191 / 192 ATA           | ATA 402                      | —                               |
| Poly         | SPIP 300             | 15 years from MFG date | DP 9841                       | Poly Edge E100               | T34W                            |
| Poly         | SPIP 301             | 15 years from MFG date | DP 9841                       | Poly Edge E100               | T34W                            |
| Poly         | SPIP 320 / 330       | 15 years from MFG date | DP 9841                       | Poly Edge E100               | T34W                            |
| Poly         | SPIP 321 / 331 / 335 | 15 years from MFG date | DP 9841                       | Poly Edge E100               | T34W                            |
| Poly         | SPIP 430             | 15 years from MFG date | DP 9841                       | Poly Edge E100               | T34W                            |
| Poly         | SPIP 450             | 15 years from MFG date | DP9851                        | Poly Edge E220               | T73W                            |
| Poly         | SPIP 500             | 15 years from MFG date | DP9851                        | Poly Edge E220               | T73W                            |

| Manufacturer | Model               | End of Service         | Recommended Cisco Replacement | Recommended Poly Replacement | Recommended Yealink Replacement |
|--------------|---------------------|------------------------|-------------------------------|------------------------------|---------------------------------|
| Poly         | SPIP 501            | 15 years from MFG date | DP9851                        | Poly Edge E220               | T73W                            |
| Poly         | SPIP 550            | 15 years from MFG date | DP9851                        | Poly Edge E220               | T73W                            |
| Poly         | SPIP 560            | 15 years from MFG date | DP9851                        | Poly Edge E220               | T73W / T73U                     |
| Poly         | SPIP 600            | 15 years from MFG date | DP9861                        | Poly Edge E320 / E350        | T73W / T73U                     |
| Poly         | SPIP 601            | 15 years from MFG date | DP9861                        | Poly Edge E320 / E350        | T73W / T73U                     |
| Poly         | SPIP 650            | 15 years from MFG date | DP9861                        | Poly Edge E320 / E350        | T73W / T73U                     |
| Poly         | SPIP 670            | 15 years from MFG date | DP9861                        | Poly Edge E320 / E350        | T74W / T74U                     |
| Poly         | SSIP 4000           | 15 years from MFG date | —                             | Poly Trio 8300               | Yealink CP925                   |
| Poly         | SSIP 5000           | 15 years from MFG date | —                             | Poly Trio 8300               | Yealink CP925                   |
| Poly         | SSIP 6000           | 15 years from MFG date | —                             | Poly Trio 8300               | Yealink CP925                   |
| Poly         | SSIP 7000           | 15 years from MFG date | —                             | Poly Trio C60                | Yealink CP965                   |
| Poly         | VVX101              | 15 years from MFG date | —                             | Poly Edge E100               | —                               |
| Poly         | VVX201              | 15 years from MFG date | —                             | Poly Edge E100               | —                               |
| Poly         | VVX300, 301         | 15 years from MFG date | —                             | Poly Edge E100               | —                               |
| Poly         | VVX310, 311         | 15 years from MFG date | —                             | Poly Edge E320               | —                               |
| Poly         | VVX400,401,410,4 11 | 15 years from MFG date | —                             | Poly Edge E450               | —                               |
| Poly         | VVX500, 501         | 15 years from MFG date | —                             | Poly Edge E450               | —                               |
| Poly         | VVX600,601          | 15 years from MFG date | —                             | Poly Edge E550               | —                               |